

Reserve Analysis • Property Inspection • Construction Consultants

March 17, 2009

Heritage Place Homeowners Association, Inc. C/o Association Management Agency 558 Castle Pines Parkway, #409 Castle Rock, Colorado 80108

**Attention: Karrie Ezell** 

**Re:** Reserve Analysis, UPDATED 2009 VERSION

Dear Ms. Ezell and Board of Directors:

As requested, Bradley Property Consultants, Inc. updated the 2005 version of the reserve analysis for Heritage Place Homeowners Association, located in Centennial, Colorado. The 2005 version of the reserve analysis was completed on April 7, 2005. This 2009 updated version of the reserve analysis reflects the current conditions on the project.

This is the updated 2009 version of the reserve analysis updated from the 2005 version. The reserve analysis was reviewed and the property was inspected in January and February 2009. The reserve analysis categories were reviewed and modified to address future and recent expenditures. This update used recent expenditures and current information on past replacements from the management company. The update reflects the expected position of the Association in 2009. The revisions and updating has brought the reserve analysis up to date with current replacement costs for the project components. The proposed maintenance expectations and comments by the management were very valuable in revising this document. The Association may wish to consider adding or deleting some categories and possibly phasing more of the categories to spread the financial responsibilities over a number of years. The phasing can be done as a revision to this document.

### CHANGES MADE TO THE 2005 VERSION OF THE RESERVE ANALYSIS TO ARRIVE AT THIS UPDATE AND REVISION:

Unit abbreviations used the Reserve Analysis table: SF= square feet, LF= lineal feet, SY= square yard, LS= lump sum, EA= each, REPL.= replacement, ECON.= economic

1. Project categories were expanded and aged accordingly. The categories were reviewed and updated for current replacement costs. Typically all the categories were brought up to current replacement costs in today's dollars. The new list of categories should be reviewed by the Association to make sure the concerns of the community are met.

### 2. Modified inventory list categories:

- a. The sprinkler system category was changed to reflect the current and historical expenses paid for repairs and modifications. After discussions with the land-scape contractor, it was determined this system would probably not be replaced entirely at one time in the future due to the size and site conditions. As the sprinkler system breaks down in small areas and those areas are being repaired or replaced. Historically the Association is spending approximately \$7,000.00 to \$10,000.00 per year on sprinkler repairs. Some areas are starting to experience underground line breaks from tree roots and aging. We have included a line item in the reserve analysis for sprinkler repairs and sectional replacements on an on going schedule. This new estimate is spending an additional \$25,000.00 every five years for major sprinkler repairs and upgrades. If the Association wishes to cover this expense in their operations budget, then the reserve analysis can be revised to eliminate this category.
- b. Wood fence was changed to reflect the replacement of the fence along Caley Avenue in two years. The replacement has been bid to install stucco posts and attempt to reuse the fence material. In the reserve analysis we used the estimated of stucco posts with new fence material. The Association can change this category one a firm decision has been made on how they are going to replace this fence.
- c. The wood fence along Arapahoe Road is now a separate category.
- d. Concrete repairs and drainage repairs have been a major expense to the Association in 2008.
- e. Staining and fence repairs were upgraded to current costs.
- f. Painting and repairing the stucco fence was upgraded to current costs.
- g. Wall costs were ungraded to reflect the improvements the Association has done over the last three years.
- 3. The estimated life for each category was examined and recalculated to reflect the category's current condition and age at the start of 2009.

### 4. The amount of total reserves available at the time of this revision was \$83,230.00.

The work performed consisted of site inspections and field measurements to determine the condition and value of items for which the Association is responsible for repair and replacement. This information was used to compile a reserve analysis inventory list. The reserve analysis estimates remaining economic life of the items in the inventory list, replacement costs, and prorates existing reserves to these items. The analysis then estimates future contributions to project reserves so adequate funds will be available for future repairs and replacements.

### Reserve Analysis Summary and Explanation of Terms

The analysis covers the common areas and items the Association is responsible for repairing and replacing. The Association has determined these items, or inventory list, by interpretation of the Declarations and Covenants for the Association and the historical maintenance schedule on the project. The inventory list should be reviewed and modified according to the actual needs of the Association.

The analysis also uses the relationship of cost replacement and remaining life to determine future reserve needs. An explanation of the terms and column headings as used within the reserve analysis table follows:

### COMMON AREA

The common area covers the common area landscaping, sidewalks, perimeter fences, lighting, and other items that are in common use by all members of the Association. It includes the sprinkler system and fixed items within the landscaped area. The non-irrigated landscape areas were not included. We have included an inventory list in the Reserve Analysis Table. Please refer to the inventory list and the other sections of the report for specific comments on individual reserve analysis items.

Some long lasting items were not included in the analysis since they should survive the assumed economic life of the project. This analysis uses a 50-year useful economic life as a basis for replacement items. Most items considered to have an expected life of 50 years or longer were not included in the replacement schedule. These items include building foundations and internal structural components. Small or low cost items under \$2,000.00 were not included since these repairs and replacements tend to be funded through the annual operating budget rather than from capital reserves.

### **DEFINITION OF TERMS USED IN THE RESERVE ANALYSIS TABLE**

### **Estimated Salvage Value**

"Estimated Salvage Value" specifically relates to items which, by their nature, will not need total replacement at the end of their assumed economic life. The considerations affecting salvage value are its long-lasting components or parts, maintenance schedule, recent repairs or replacements, and importance to the appearance of the project. Items that directly affect the appearance and function of the project tend to be maintained more completely and more often. Hard scape items such as asphalt and concrete tend to be repaired as necessary rather than all at once. Some portions will last as long as the economic life of the project while other parts will need repairs, but not full replacement.

The "Estimated Salvage Value" identifies those items that will not need total replacement upon reaching their assumed economic life. The percentages noted on the schedule are based on our experience. They can be modified after discussions with the Association regarding areas and percentages best fitting with the overall maintenance philosophy of the project.

### Replacement Costs

Replacement costs were arrived at using estimating procedures and our experience with bidding current market prices. The amounts are in current dollars and are estimates. They assume major repairs or replacements will be done all at the same time.

The actual costs for replacements may vary considerably depending on economic conditions, contract specifications, technological advances, regulatory changes, and maintenance schedules. No adjustments for inflation were made for replacement costs. Inflation values fluctuate and are not reliably defined. Over a long period of time, inflation is often offset by investment credits or interest earned. The varying rates and changes to the project can be reflected by annual updates to the reserve analysis. We recommend annual updates to the reserve analysis to account for any substantial changes directly affecting the cost of replacements. Such changes would include insurance settlements, natural disasters, or unknown conditions requiring significant expenditures.

### **Estimated Economic Life**

The estimated economic life and life left are our estimates obtained from published manuals, accepted industry standards, and our experience with similar projects. The estimated life remaining

for the reserve items was determined after our visual inspections and discussions with the management and a board member. The project was constructed in the early 1970's. The average age of the components had to be interpreted for each inventory item since some items will age faster than others. The major replacements and repairs are reflected in the "Remaining Economic Life" and "Estimated Salvage Value" columns.

The "Desired Reserve Budget," "Reserves Available," and "Annual Deposit" are arrived at after determining the estimated replacement costs and economic life span of the reserve items.

### **Desired Reserve Budget**

The "Desired Reserve Budget" is the estimated amount that would have been deposited by now if the inventory items had been included in a reserve deposit schedule from the beginning of the project. Each item's estimated replacement cost is divided by its proposed economic life and then multiplied by its age to arrive at the desired reserve budget. This is a "best case" scenario to show what would have been reserved to date for each item. These figures are used to develop a percentage or proportional relationship for each item as it relates to the total "Desired Reserve Budget." The item percentage is used to distribute the present reserves and analyze future needs.

### Reserves Available

The actual reserves available are distributed to each inventory item in proportion to the "Desired Reserve Budget" figures. The proportion or percentage for each item as determined by the "Desired Reserve Budget" is multiplied by the actual reserves on hand to arrive at the reserve value for each item. The reserves available for this update were \$83,230.00.

### **Proposed Initial Deposit**

The initial annual deposit for each item is equal to the difference between the estimated replacement cost and the reserves available, divided by the years of life remaining for the item. This is an estimated annual deposit for each item from this time forward. The deposits attempt to achieve the desired replacement reserves in the future.

### **Average Annual Contribution**

The annual deposits required over the life of the project will fluctuate as reserves are saved and spent in anticipated cycles. We have attempted to account for these cycles by calculating the average annual deposits necessary for a 40 year period. In calculating your requirements, the initial deposit

brings your reserve balance closer to what it should be now and the average deposit lets the association gauge what level of savings to achieve in the future.

You must consider that these amounts are determined as the best possible condition and to achieve the best reserve balance requires some long term planning. In most cases this amount is hard to achieve, especially when the reserves are analyzed for the expected life of all the project categories. Most Associations are doing very well if they can achieve 70-80% of the proposed annual contributions and recommended reserve balances. A part of the planning process may be to establish a reasonable goal and attempt to reach the best result possible.

As stated previously, we recommend annual updates to the reserve analysis to account for replacements, changes in replacement costs, and changing interest rates. Interest earned will tend to offset inflation. Attempting to forecast into the future is tenuous at best. We believe it is preferable to make simple annual changes to the analysis and make decisions based on the most recent information available. The reserve analysis is a working document and should be adjusted as necessary to meet the needs and desires of the Association and reflect changing conditions.

We performed this analysis at the request of the Board of Directors of Heritage Place Homeowners Association, Inc. The report is intended for the Association's exclusive use and should not be used for contracting work or relied upon by any other party. The analysis reflects conditions within the property that could be examined visually and is limited to the extent of the report. The analysis is also based upon representations made by Heritage Place Homeowners Association, Inc. in regard to existing reserve fund balances, recent replacements or repairs, and interpretation of the Declarations and Covenants for the project. While reasonable effort was made to ascertain the condition of the property and/or equipment within, it is not to be construed as a guarantee or warranty of the property or equipment therein, nor does it imply that all components will function properly on or after the date of this report. Acceptance of this report by the Association constitutes the agreement of the Association that the liability of Bradley Property Consultants, Inc. for any errors or omissions on negligent misrepresentations herein is limited to the fee paid for this report and that there shall be no liability whatsoever for incidental or consequential damages. Unless otherwise noted in the report, no sampling, testing, or dismantling of any equipment, systems or structural components of the property, other than the visual inspection, was performed. Further, no inspections or tests for soil quality or stability, asbestos, PCBs, or any other hazardous materials were undertaken nor was the quality or adequacy of the water and sewer service to the property analyzed. The inspections addressed herein were not undertaken to address any specific use or purpose contemplated by the Association other than what was stated in the report. This report does not in any way address the property's compliance with any federal, state, or local laws, rules, regulations, or ordinances.

We believe the analysis will provide a useful planning guide. Actual experience in replacing items may differ significantly from the estimates given. Again, we recommend annual updates to the analysis to reflect changes to current conditions.

If you have any questions or require further information, please contact our office at any time.

Very truly yours,

BRADLEY PROPERTY CONSULTANTS, INC.

Stephen M. Bradley, President

Enclosures and Attachments: Updated 2009 Version

- Replacement and Reserve Analysis Table
- Tables and Graphs of Reserve Balances Over Remaining Life of Components
- Table of Projected Capital Expenses by Year



RESERVE ANALYSIS 2009 VERSION: 3-17-09

	8	
	8	₹ Ø
	ğ	EGS
	ř	<u> </u>
	٥	
		8 1
		≥₩
		M =
		₩ Ş
		***************************************
	A	¥
	ĸ	# 5 %
	S	ଛ ଅ
	Ω	<u>w</u> w
	1	田田の
	弘	ጟቔ፟፟፟፟
		利田の
	S	있밤똣
		111
	S	S S
:	ш	ı Z Ö
	١	<u>با</u> لي
	Ž	m o ∾
		<b>L</b> O
	***	
		<u>о</u> н
	-	ME SO
	й	2 <b>3</b> °
		Ø .
		È
		<u> </u>
		ō
		5
		5
7		
19		
70		
19	3	z
ite:	S: 4	
da.	Ę	<u> </u>
ec	=	5
Project date: 1970-1974	Total units: 446	n N
•	_	

COMMON AREA									
Sprinkler system: repair & replace	rs	-	25000.00	25,000	S	4	5,000	1,860	5,785
Landscape refurbish/tree trim	rs	<b>~</b>	20000.00	20,000	2	က	8,000	2,975	5,675
Concrete repairs: walks & pans	rs	_	30000.00	30,000	10	6	3,000	1,116	3,209
6' fence w/stucco post: Caley Ave.	<b>Ľ</b>	2,820	70.25	198,105	52	7	182,257	67,783	65,161
6' fence: Arapahoe Rd.	<b>Ľ</b>	1,140	26.00	29,640	52	10	17,784	6,614	2,303
Stain wood fence	4	3,960	2.00	7,920	ß	4	1,584	589	1,833
Stucco fence: paint & repair	<b>ٿ</b>	2,430	4.25	10,328	5	4	2,066	768	2,390
Signage	P	_	00.0009	9,000	20	15	1,500	558	363
Lighting	rs	_	8000.00	8,000	9	ω	1,600	595	926
Rock retaining walls	rs	-	10000.00	10,000	10	ဝ	1,000	372	1,070
							223,790	83,230	88,714
CONTINGENCY		%0					0	0	0
		TOTAL REPLACEME	MENT COST ——	344,993					

BPC, Inc., 03/2009

88,714

83,230

223,790

TOTAL DESIRED RESERVES TOTAL RESERVES AVAILABLE

**40 YR AVERAGE ANNUAL CONTRIBUTION** 

TOTAL INITIAL CONTRIBUTION



## RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

2009 VERSION: 3-17-09

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

YEAR 2015 YEAR 2014 10 YEAR 2013 9 YEAR 2012 8 YEAR 2011 YEAR 2010 YEAR 2009 5 YEAR 2008 YEAR 2007 3 YEAR 2006 2 YEAR 2005 DESCRIPTION

COMMONAREA											
Sprinkler system: repair & replace	7,645	13,430	19,215	25,000	5,000	10,000	15,000	20,000	25,000	5,000	10,000
Landscape refurbish/tree trim	8,650	14,325	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000
Concrete repairs: walks & pans	4,325	7,534	10,744	13,953	17,163	20,372	23,581	26,791	30,000	3,000	000'9
6' fence w/stucco post: Caley Ave.	132,944	198,105	7,924	15,848	23,773	31,697	39,621	47,545	55,469	63,394	71,318
6' fence: Arapahoe Rd.	8,917	11,219	13,522	15,824	18,127	20,430	22,732	25,035	27,337	29,640	1,186
Stain wood fence	2,422	4,255	6,087	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168
Stucco fence: paint & repair	3,158	5,548	7,938	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131
Signage	921	1,283	1,646	2,009	2,372	2,735	3,098	3,460	3,823	4,186	4,549
Lighting	1,521	2,446	3,372	4,298	5,223	6,149	7,074	8,000	800	1,600	2,400
Rock retaining walls	1,442	2,511	3,581	4,651	5,721	6,791	7,860	8,930	10,000	1,000	2,000
BASE RESERVES	171,944	260,657	94,029	103,831	89,028	117,471	145,915	174,359	174,677	119,469	116,751
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	0	(198,105)	(20,000)	(43,248)	0	0	0	(28,000)	(83,248)	(29,640)	0
ANNUAL DEPOSIT	88,714	88,714	31,477	29,802	28,444	28,444	28,444	28,444	28,318	28,039	26,922
TOTAL RESERVES	171,944	62,552	74,029	60,584	89,028	117,471	145,915	146,359	91,430	89,829	116,751
BPC, Inc., 03/2009											



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

2009 VERSION: 3-17-09

COMMON AREA											
Sprinkler system: repair & replace	15,000	20,000	25,000	2,000	10,000	15,000	20,000	25,000	5,000	10,000	15,000
Landscape refurbish/tree trim	16,000	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000	16,000
Concrete repairs: walks & pans	6,000	12,000	15,000	18,000	21,000	24,000	27,000	30,000	3,000	6,000	0006
6' fence w/stucco post: Caley Ave.	79,242	87,166	95,090	103,015	110,939	118,863	126,787	134,711	142,636	150,560	158,484
6' fence: Arapahoe Rd.	2,371	3,557	4,742	5,928	7,114	8,299	9,485	10,670	11,856	13,042	14,227
Stain wood fence	4,752	6,336	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168	4,752
Stucco fence: paint & repair	6,197	8,262	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131	6,197
Signage	4,912	5,274	5,637	6,000	300	009	006	1,200	1,500	1,800	2,100
Lighting	3,200	4,000	4,800	2,600	6,400	7,200	8,000	800	1,600	2,400	3,200
Rock retaining walls	3,000	4,000	5,000	9,000	7,000	8,000	000,6	10,000	1,000	2,000	3,000
BASE RESERVES	143,673	170,595	177,517	161,192	182,051	208,911	235,770	234,629	178,241	205,100	231,960
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	0	(20,000)	(43,248)	(0000)	0	0	(28,000)	(83,248)	0	0	0
ANNIAI DEPOSIT	26 922	26.92	26.92	26.922	26.850	96.850	96 850	058.96	26.850	058.96	058 96
					Color	CO'0	1000	1000	10,00	20,00	100to=
TOTAL RESERVES	143,673	150,595	134,270	155,192	182,051	208,911	207,770	151,382	178,241	205,100	231,960
BPC, Inc., 03/2009											1



## RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

2009 VERSION: 3-17-09

1588 S. Clarkson St., Denver, CO 80210 Phone: 303-232-0252 Fax 303-232-3243

1
<b>E</b> .
2 S 8
3 .
2 5 8
¥ % _
H 0 m
3 5 6 3 4 8
78.0
~
380
2 0 Z
~
4 65 80
3 0 K
~
EAR 031 27
20 X
~
26 32 26 28
<b>5</b> 8
<b>~</b>
EAR 25 929
> 0
<b>2</b>
2 2 2
<b>~</b>
882
8
Ē
<b>*</b>
မ
<u> </u>

COMMON AREA:											
Sprinkler system: repair & replace	20.000	25.000	2 000	10 000	15 000	20 000	25 000	000 \$	10 000	15.000	20,000
Landscape refurbish/free trim	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000	16,000	20,000
Concrete repairs: walks & pans	12,000	15,000	18,000	21,000	24,000	27,000	30,000	3,000	6,000	000,6	12,000
6' fence w/stucco post: Caley Ave.	166,408	174,332	182,257	190,181	198,105	7,924	15,848	23,773	31,697	39,621	47,545
6' fence: Arapahoe Rd.	15,413	16,598	17,784	18,970	20,155	21,341	22,526	23,712	24,898	26,083	27,269
Stain wood fence	6,336	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168	4,752	6,336
Stucco fence: paint & repair	8,262	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131	6,197	8,262
Signage	2,400	2,700	3,000	3,300	3,600	3,900	4,200	4,500	4,800	5,100	5,400
Lighting	4,000	4,800	2,600	6,400	7,200	8,000	800	1,600	2,400	3,200	4,000
Rock retaining walls	4,000	5,000	6,000	7,000	8,000	0006	10,000	1,000	2,000	3,000	4,000
BASE RESERVES	258,819	265,678	249,290	276,149	303,009	131,763	130,622	74,234	101,093	127,953	154,812
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	(20,000)	(43,248)	0	0	(198,105)	(28,000)	(83,248)	0	0	0	(20,000)
ANNIAI DEPOSIT	058 92	26.850	058.96	058.96	26.850	058.90	058 96	058.90	058 96	36 950	076 96
	Codo	CO.	(CO)0=	Color	Cotor	CONON	C0404	100,004	40,037	40,037	70007
TOTAL RESERVES	238,819	222,431	249,290	276,149	104,904	103,763	47,375	74,234	101,093	127,953	134,812
BPC. Inc., 03/2009											



## RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

2009 VERSION: 3-17-09

Sprinkler system: repair & replace         25,000         5,000         10,000         15,           Landscape refurbish/free trim         4,000         8,000         12,000         16,           Concrete repairs: walks & pans         15,000         18,000         24,000         24,           6' fence w/stucco post: Caley Ave.         55,469         63,394         71,318         79,           6' fence: Arapahoe Rd.         28,454         29,640         1,186         2,           Stain wood fence         7,920         1,584         3,168         4,           Stucco fence: paint & repair         10,338         2,066         4,131         6,           Signage         5,700         6,000         5,600         6,400         7,           Brock retaining walls         5,000         6,000         7,000         8,	10,000     15,000     20,000       12,000     16,000     20,000       21,000     24,000     27,000       71,318     79,242     87,166       1,186     2,371     3,557       3,168     4,752     6,336       4,131     6,197     8,262	25,000 4,000 30,000 5 95,090 7 4,742 5 7,920	5,000 8,000 3,000 103,015 5,928
4,000     8,000     12,000       15,000     18,000     21,000       55,469     63,394     71,318       28,454     29,640     1,186       7,920     1,584     3,168       10,328     2,066     4,131       5,700     6,000     300       4,800     5,600     6,400       5,000     6,000     7,000	16,000 24,000 79,242 2,371 4,752 6,197		8,000 3,000 103,015 5,928
15,000 18,000 21,000 55,469 63,394 71,318 28,454 29,640 1,186 7,920 1,584 3,168 10,328 2,066 4,131 5,700 6,000 300 4,800 5,600 6,400 5,000 6,000 7,000	24,000 79,242 2,371 4,752 6,197		3,000 103,015 5,928 1,584
55,469 63,394 71,318 28,454 29,640 1,186 7,920 1,584 3,168 10,328 2,066 4,131 5,700 6,000 300 4,800 5,600 6,400 5,000 6,000	79,242 2,371 4,752 6,197		103,015 5,928 1,584
28,454 29,640 1,186 7,920 1,584 3,168 10,328 2,066 4,131 5,700 6,000 300 4,800 5,600 6,400 5,000 6,000	2,371 4,752 6,197		5,928
7,920 1,584 3,168 10,328 2,066 4,131 5,700 6,000 300 4,800 5,600 6,400 5,000 6,000	4,752 6,197		1.584
5,700 6,000 300 4,800 5,600 6,400 5,000 6,000 7,000	6,197		
5,700 6,000 300 4,800 5,600 6,400 3ining walls 5,000 6,000 7,000			2,066
4,800 5,600 6,400 5,000 6,000 7,000	009		1,500
2,000 6,000 7,000	7,200		1,600
2005	8,000	10,000	1,000
BASE RESERVES 161,671 145,283 136,502 163,	36,502 163,362 190,221	189,080	132,692
CONTINGENCY 0 0 0 0	0 0	0	0
<b>CAPITAL EXPENSES</b> (43,248) (35,640) 0	0 0 (28,000)	(83,248)	0

BPC, Inc., 03/2009

132,692

26,859

26,859

26,859

26,859

26,859

26,859

26,859

ANNUAL DEPOSIT
TOTAL RESERVES

162,221


163,362

109,643



Phone: 303-232-0252 Fax: 303-232-3243 1588 S. Clarkson St., Denver, CO 80210






		RESERVES ON I	HAND YEAR 1		\$83,230		VALUE OF RES	ERVE ITEMS		\$344,993	
	Ш	<b>ENDING BALANCE YEAR 11</b>	<b>CE YEAR 11</b>		\$116,751		AVERAGE CAPITAL EXPENSE	ITAL EXPENSE		\$36,567	
	<b>*</b>	VERAGE BALA	NCE		\$105,990		AVERAGE DEPOSIT	OSIT		\$39,615	
	-	2	က	4	ß	9	7	80	6	10	7
	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
ES	0		(20,000)	(43,248)	0	0	0	(28,000)	(83,248)	(29,640)	0
TS	88,714	88,714	31,477	29,802	28,444	28,444	28,444	28,444	28,318	28,039	26,922
Si	171.944		74.029	60.584	80.028	117.471	145.915	146.359	91.430	89.829	116.751

	_	2	ო	4	S	9	7	80	တ	9	1
YEAR	2002	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
CAPITAL EXPENSES	0	(198,105)	(20,000)	(43,248)	0	0	0	(28,000)	(83,248)	(29,640)	0
ANNUAL DEPOSITS	88,714	88,714	31,477	29,802	28,444	28,444	28,444	28,444	28,318	28,039	26,922
TOTAL RESERVES	171,944	62,552	74,029	60,584	89,028	117,471	145,915	146,359	91,430	89,829	116,751

### Property Inspection • Construction Consultants BRADLEY PROPERTY CONSULTANTS

1588 S. Clarkson St., Denver, CO 80210 Phone: 303-232-0252 Fax 303-232-3243



	<b>α</b>	ESERVES ON I	<b>VES ON HAND YEAR 12</b>		\$146,359	-	VALUE OF RESERVE ITEMS	ERVE ITEMS		\$344,993	
	E	ENDING BALAN	<b>BALANCE YEAR 22</b>		\$231,960		<b>AVERAGE CAPITAL EXPENSI</b>	TAL EXPENSE		\$16,409	
	¥	VERAGE BALANCE	NCE		\$177,195		AVERAGE DEPOSIT	SIT		\$26,882	
	12	13	4	15	91	1	18	19	20	21	22
YEAR	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026
CAPITAL EXPENSES	0	(20,000)	(43,248)	(0000)	0	0	(38,000)	(83,248)	0	0	0
ANNUAL DEPOSITS	726'97	26,922	26,922	26,922	26,859	26,859	26,859	26,859	26,859	26,859	26,859
TOTAL RESERVES	143,673	150,595	134,270	155,192	182,051	208,911	207,770	151,382	178,241	205,100	231,960


BPC, Inc., 03/2009



Property Inspection • Construction Consultants

1588 S. Clarkson St., Denver, CO 80210 Phone 303-232-0252 Fax: 303-232-3243






	2	RESERVES ON	<b>RVES ON HAND YEAR 23</b>	3	\$151,382	<b>^</b>	ALUE OF RESERVE ITEMS	RVE ITEMS		\$344,993	
	Ш	G BA	LANCE YEAR 33		\$134,812	¥	VERAGE CAPITAL EXPENSE	TAL EXPENSE		\$35,691	
	¥	AGE BA	LANCE		\$152,802	₹	VERAGE DEPOSIT	SIT		\$26.859	
	23	24	25	56	27	28	29	30	31	32	33
YEAR	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037
CAPITAL EXPENSES	(20,000)	(43,248)	0	0	(198,105)	(28,000)	(83,248)	0	0	0	(20,000)
ANNUAL DEPOSITS	26,859	26,859	26,859	26,859	26,859	26,859	26,859	26.859	26.859	26,859	26,859
TOTAL RESERVES	238,819	222,431	249,290	276,149	104,904	103,763	47,375	74,234	101,093	127,953	134,812

BPC, Inc., 03/2009



Phone: 303-232-0252 Fax: 303-232-3243 1588 S. Clarkson St., Denver, CO 80210





- Janeary Control of the Control of		8	1	· ·	30	,
\$26,859	AVERAGE DEPOSIT	999	\$132,668		ERAGE BALANCE	8
\$39,882	AVERAGE CAPITAL EXPENSE	692	\$132,692	EAR 40	IDING BALANCE YEAR 40	面
\$344,993	VALUE OF RESERVE ITEMS	234	\$74,234	D YEAR 34	SERVES ON HAND YEAR 34	쮼

	4,	င်	ş	3	ž	SS SS	40
YEAR	2038	2039	2040	2041	2042	2043	2044
CAPITAL EXPENSES	(43,248)	(35,640)	0	0	(28,000)	(83,248)	0
ANNUAL DEPOSITS	26,859	26,859	26,859	26,859	26,859	26,859	26,859
TOTAL RESERVES	118,424	109,643	136,502	163,362	162,221	105,833	132,692

						:	
YEAR	2038	2039	2040	2041	2042	2043	Ñ
CAPITAL EXPENSES	(43,248)	(35,640)	0	0	(28,000)	(83,248)	
ANNUAL DEPOSITS	658'97	26,859	26,859	26,859	26,859	26,859	26,
TOTAL RESERVES	118,424	109,643	136,502	163,362	162,221	105,833	132,



### RESERVE ANALYSIS- Projected Capital Expenses By Year

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

2009 VERSION: 3-17-09

YEAR 2015 YEAR 2014 YEAR 2013 YEAR 2012 YEAR 2011 YEAR 2010 YEAR 2009 YEAR 2008 YEAR 2007 YEAR 2006 YEAR 2005 CAPITAL EXPENSES SECTION

COMMONAREA		į	;								
Sprinkler system: repair & replace	0	0	0	25,000	0	0	0	0	25,000	0	0
Landscape refurbish/tree trim	0	0	20,000	0	0	0	0	20,000	0	0	0
Concrete repairs: walks & pans	0	0	0	0	0	0	0	0	30,000	0	0
6' fence w/stucco post: Caley Ave.	0	198,105	0	0	0	0	0	0	0	0	0
6' fence: Arapahoe Rd.	0	0	0	0	0	0	0	0	0	29,640	0
Stain wood fence	0	0	0	7,920	0	0	0	0	7,920	0	0
Stucco fence: paint & repair	0	0	0	10,328	0	0	0	0	10,328	0	0
Signage	0	0	0	0	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	0	0	8,000	0	0	0
Rock retaining walls	0	0	0	0	0	0	0	0	10,000	0	0
Capital Expense	0	198,105	20,000	43,248	0	0	0	28,000	83,248	29,640	0

BPC, Inc., 03/2009



1588 S. Clarkson St., Denver, CO 80210

### HERITAGE PLACE HOMEOWNERS ASSOCIATION

RESERVE ANALYSIS- Projected Capital Expenses By Year

2009 VERSION: 3-17-09

CAPITAL EXPENSES SECTION	YEAR 2016 12	YEAR 2017 13	YEAR 2018 14	YEAR 2019 15	Y EAR 2020 16	YEAR 2021 17	VEAR 2022 18	YEAR Y 2023 2 19	YEAR 2024 20	FEAR YEAR 2025 2026 21 22	
COMMON AREA											
Sprinkler system: repair & replace	0	0	25,000	0	0	0	0	25,000	0	0	0
Landscape refurbish/tree trim	0	20,000	0	0	0	0	20,000	0	0	0	0
Concrete repairs: walks & pans	0	0	0	0	0	0	0	30,000	0	0	0
6' fence w/stucco post: Caley Ave.	0	0	0	0	0	0	0	0	0	0	0
6' fence: Arapahoe Rd.	0	0	0	0	0	0	0	0	0	0	0
Stain wood fence	0	0	7,920	0	0	0	0	7,920	0	0	0
Stucco fence: paint & repair	0	0	10,328	0	0	0	0	10,328	0	0	0
Signage	0	0	0	6,000	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	0	8,000	0	0	0	0
Rock retaining walls	0	0	0	0	0	0	0	10,000	0	0	0
Capital Expense	0	20,000	43,248	6,000	0	0	28,000	83,248	0	0	0



### RESERVE ANALYSIS- Projected Capital Expenses By Year

2009 VERSION: 3-17-09

1588 S. Clarkson St., Denver, CO 80210 Phone: 303-232-0252 Fax: 303-232-3243

	₹ % %
	200
	~
	₹ <del>6</del> 6
	3 O E
	***************************************
	<b>4</b> ,
į	388
i	<b>∑</b> .∾
	***************************************
	<b>3</b>
	<b>₩</b>
	. A
į	
	<b>~</b> 23 ~
	H & X
	₹
	₹ 8 ∞
	200
	<b>~</b>
	₹ E Z
	> ~
	₩
	<b>7</b> 8 6
	200
	<b>.</b>
	3 2 %
	>~
	₹ ∞
	. <del></del>
	<b>*</b>
	<b>₹</b> 2 m
	28.7
	5
	<b>-</b>
	LI C
	ळ
	S
	<u></u>
	ញ៍
	<b></b>
	u)
2. 20 20 000 1 200 E0 000 1000 1000 1000 1	3

COMMON AREA											
Sprinkler system: repair & replace	0	25,000	0	0	0	0	25,000	0	0	0	0
Landscape refurbish/tree trim	20,000	0	0	0	0	20,000	0	0	0	0	20,000
Concrete repairs: walks & pans	0	0	0	0	0	0	30,000	0	0	0	0
6' fence w/stucco post: Caley Ave.	0	0	0	0	198,105	0	0	0	0	0	0
6' fence: Arapahoe Rd.	0	0	0	0	0	0	0	0	0	0	0
Stain wood fence	0	7,920	0	0	0	0	7,920	0	0	0	0
Stucco fence: paint & repair	0	10,328	0	0	0	0	10,328	0	0	0	0
Signage	0	0	0	0	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	8,000	0	0	0	0	0
Rock retaining walls	0	0	0	0	0	0	10,000	0	0	0	0
Capital Expense	20,000	43,248	0	0	198,105	28,000	83,248	0	0	0	20,000



RESERVE ANALYSIS- Projected Capital Expenses By Year

1588 S. Clarkson St., Denver, CO 80210

2009 VERSION: 3-17-09

YEAR 2044 YEAR 2043 VEAR 2842 YEAR 2041 YEAR 2040 YEAR 2039 YEAR 2038 CAPITAL EXPENSES SECTION Phone: 303-232-0252 Fax: 303-232-3243

COMMON AREA							
Sprinkler evetem: repair & replace	25,000	C	o	0	0	25 000	
Landscape refurbish/tree trim	0	0	0	0	20,000	0	0
Concrete repairs: walks & pans	0	0	0	0	0	30,000	0
6' fence w/stucco post: Caley Ave.	0	0	0	0	0	0	0
6' fence: Arapahoe Rd.	0	29,640	0	0	0	0	0
Stain wood fence	7,920	0	0	0	0	7,920	0
Stucco fence: paint & repair	10,328	0	0	0	0	10,328	0
Signage	0	000'9	0	0	0	0	0
Lighting	0	0	0	0	8,000	0	0
Rock retaining walls	0	0	0	0	0	10,000	0
Capital Expense	43,248	35,640	0	0	28,000	83,248	0

BPC, Inc., 03/2009

Page: 1

### **BALANCE SHEET** HEY' LAGE BLACE HOMEOWNERS ASSOC. 🙎

### **WYKCH 31' 5002**

### **YZZETS**

### **CURRENT ASSETS**

1,211.00	 KELVID EXPENSES
(1,264.00)	ALLOWANCE FOR BAD DEBT
00.009	SPECIAL ASSESSMENTS
17,072.57	UNPAID ASSESSMENTS
70,120.58	<b>KESEKAE - WW COMBASS BANK</b>
4£.678,631	\$ CASH - OPERATING COMPASS BANK

257,619,49

TOTAL CURRENT ASSETS

64.619,782

**TOTAL ASSETS** 

### LIABILITIES AND EQUITY

### **CURRENT LIABILITIES**

	EQUITY
00.0	TOTAL LIABILITIES
00.0	TOTAL CURRENT LIABILITIES

\$ NET INCOME ENND BYTYNCE
\$

257,619,49

257,619,49

TOTAL LIABILITIES & EQUITY

**TOTAL EQUITY**