

Reserve Analysis • Property Inspection • Construction Consultants

August 3, 2009

Heritage Place Homeowners Association, Inc. C/o Association Management Agency 558 Castle Pines Parkway, #409 Castle Rock, Colorado 80108

Attention: Karrie Ezell

Re: Reserve Analysis, SECOND UPDATED 2009 VERSION

Dear Ms. Ezell and Board of Directors:

As requested, Bradley Property Consultants, Inc. updated the 2005 version of the reserve analysis for Heritage Place Homeowners Association, located in Centennial, Colorado. The 2005 version of the reserve analysis was completed on April 7, 2005. The reserve analysis was updated for 2009 on March 17, 2009. A second updated version of the reserve analysis is attached. The newest version reflects the current expense espectations of the Association to include the phased replacement of the sprinkler system, a new eight foot wood fence along Arapahoe Road, and the grouting of the rock retaining walls on the project.

This is the updated 2009 version of the reserve analysis revises the 2005 version and the first 2009 version. The reserve analysis was reviewed and the property was inspected in January and February 2009. The reserve analysis categories were reviewed and modified to address future and recent expenditures. Additional impute by the Board provided future replacement costs expectations and needs. The second 2009 update reflects the expected position of the Association going forward in 2009. The proposed maintenance expectations and comments by the Association were very valuable in revising this document. The Association may wish to consider adding or deleting some categories and possibly phasing more of the categories to spread the financial responsibilities over a number of years. The phasing can be done as a revision to this document.

CHANGES MADE TO THE RESERVE ANALYSIS TO ARRIVE AT THIS UPDATED REVISION:

Unit abbreviations used the Reserve Analysis table: SF= square feet, LF= lineal feet, SY= square yard, LS= lump sum, EA= each, REPL. = replacement, ECON. = economic

1. Project categories were expanded and aged accordingly. The categories were reviewed and updated for current replacement costs. Typically all the categories were brought

up to current replacement costs in today's dollars. The new list of categories should be reviewed by the Association to make sure the concerns of the community are met.

- 2. Modified inventory list categories:
 - a. The sprinkler system category is 35 years old and in very poor condition. It is breaking and not operating efficiently. The second update to the reserve analysis has estimated replacing the sprinkler system in phases beginning in 2010. The cost used are estimates and actual costs will vary after the Association does the necessary design work and planning.
 - b. Wood fence was changed to reflect the replacement of the fence along Caley Avenue in three years. The replacement has been bid to install stucco posts and attempt to reuse the fence material. In the reserve analysis we used the estimated of stucco posts with new fence material. The Association can change this category one a firm decision has been made on how they are going to replace this fence.
 - c. The wood fence along Arapahoe Road will be replaced with an eight foot fence. This work is expected to begin in 2012.
 - d. Concrete repairs and drainage repairs have been a major expense to the Association in 2008. Some unexpected erosion was discovered around and under the drain pans.
 - e. Staining and fence repairs were upgraded to current costs.
 - f. Painting and repairing the stucco fence was upgraded to current costs.
 - g. The rock retaining walls are now scheduled to be grouted to establish more durability and reduce the constant cost of repairs.
- 3. The estimated life for each category was examined and recalculated to reflect the category's current condition and age at the start of 2009.
- 4. The amount of total reserves available at the time of this revision as of the end of June 2009 was \$69,247.00.

The work performed consisted of site inspections and field measurements to determine the condition and value of items for which the Association is responsible for repair and replacement. This information was used to compile a reserve analysis inventory list. The reserve analysis estimates remaining economic life of the items in the inventory list, replacement costs, and prorates existing reserves to these items. The analysis then estimates future contributions to project reserves so adequate funds will be available for future repairs and replacements.

Reserve Analysis Summary and Explanation of Terms

The analysis covers the common areas and items the Association is responsible for repairing and replacing. The Association has determined these items, or inventory list, by interpretation of the Declarations and Covenants for the Association and the historical maintenance schedule on the project. The inventory list should be reviewed and modified according to the actual needs of the Association.

The analysis also uses the relationship of cost replacement and remaining life to determine future reserve needs. An explanation of the terms and column headings as used within the reserve analysis table follows:

COMMON AREA

The common area covers the common area landscaping, sidewalks, perimeter fences, lighting, and other items that are in common use by all members of the Association. It includes the sprinkler system and fixed items within the landscaped area. The non-irrigated landscape areas were not included. We have included an inventory list in the Reserve Analysis Table. Please refer to the inventory list and the other sections of the report for specific comments on individual reserve analysis items.

Some long lasting items were not included in the analysis since they should survive the assumed economic life of the project. This analysis uses a 50-year useful economic life as a basis for replacement items. Most items considered to have an expected life of 50 years or longer were not included in the replacement schedule. These items include building foundations and internal structural components. Small or low cost items under \$2,000.00 were not included since these repairs and replacements tend to be funded through the annual operating budget rather than from capital reserves.

DEFINITION OF TERMS USED IN THE RESERVE ANALYSIS TABLE

Estimated Salvage Value

"Estimated Salvage Value" specifically relates to items which, by their nature, will not need total replacement at the end of their assumed economic life. The considerations affecting salvage value are its long-lasting components or parts, maintenance schedule, recent repairs or replacements, and importance to the appearance of the project. Items that directly affect the appearance and function of the project tend to be maintained more completely and more often. Hard scape items such as asphalt and concrete tend to be repaired as necessary rather than all at once. Some portions will last as long as the economic life of the project while other parts will need repairs, but not full replacement.

The "Estimated Salvage Value" identifies those items that will not need total replacement upon reaching their assumed economic life. The percentages noted on the schedule are based on our experience. They can be modified after discussions with the Association regarding areas and percentages best fitting with the overall maintenance philosophy of the project.

Replacement Costs

Replacement costs were arrived at using estimating procedures and our experience with bidding current market prices. The amounts are in current dollars and are estimates. They assume major repairs or replacements will be done all at the same time.

The actual costs for replacements may vary considerably depending on economic conditions, contract specifications, technological advances, regulatory changes, and maintenance schedules. No adjustments for inflation were made for replacement costs. Inflation values fluctuate and are not reliably defined. Over a long period of time, inflation is often offset by investment credits or interest earned. The varying rates and changes to the project can be reflected by annual updates to the reserve analysis. We recommend annual updates to the reserve analysis to account for any substantial changes directly affecting the cost of replacements. Such changes would include insurance settlements, natural disasters, or unknown conditions requiring significant expenditures.

Estimated Economic Life

The estimated economic life and life left are our estimates obtained from published manuals, accepted industry standards, and our experience with similar projects. The estimated life remaining for the reserve items was determined after our visual inspections and discussions with the management and a board member. The project was constructed in the early 1970's. The average age of

the components had to be interpreted for each inventory item since some items will age faster than others. The major replacements and repairs are reflected in the "Remaining Economic Life" and "Estimated Salvage Value" columns.

The "Desired Reserve Budget," "Reserves Available," and "Annual Deposit" are arrived at after determining the estimated replacement costs and economic life span of the reserve items.

Desired Reserve Budget

The "Desired Reserve Budget" is the estimated amount that would have been deposited by now if the inventory items had been included in a reserve deposit schedule from the beginning of the project. Each item's estimated replacement cost is divided by its proposed economic life and then multiplied by its age to arrive at the desired reserve budget. This is a "best case" scenario to show what would have been reserved to date for each item. These figures are used to develop a percentage or proportional relationship for each item as it relates to the total "Desired Reserve Budget." The item percentage is used to distribute the present reserves and analyze future needs.

Reserves Available

The actual reserves available are distributed to each inventory item in proportion to the "Desired Reserve Budget" figures. The proportion or percentage for each item as determined by the "Desired Reserve Budget" is multiplied by the actual reserves on hand to arrive at the reserve value for each item. The reserves available for this update as of the end of June 2009 was \$69,247.00.

Proposed Initial Deposit

The initial annual deposit for each item is equal to the difference between the estimated replacement cost and the reserves available, divided by the years of life remaining for the item. This is an estimated annual deposit for each item from this time forward. The deposits attempt to achieve the desired replacement reserves in the future.

Average Annual Contribution

The annual deposits required over the life of the project will fluctuate as reserves are saved and spent in anticipated cycles. We have attempted to account for these cycles by calculating the average annual deposits necessary for a 40 year period. In calculating your requirements, the initial deposit brings your reserve balance closer to what it should be now and the average deposit lets the association gauge what level of savings to achieve in the future.

You must consider that these amounts are determined as the best possible condition and to achieve the best reserve balance requires some long term planning. In most cases this amount is hard to achieve, especially when the reserves are analyzed for the expected life of all the project categories. Most Associations are doing very well if they can achieve 70-80% of the proposed annual contributions and recommended reserve balances. A part of the planning process may be to establish a reasonable goal and attempt to reach the best result possible.

As stated previously, we recommend annual updates to the reserve analysis to account for replacements, changes in replacement costs, and changing interest rates. Interest earned will tend to offset inflation. Attempting to forecast into the future is tenuous at best. We believe it is preferable to make simple annual changes to the analysis and make decisions based on the most recent information available. The reserve analysis is a working document and should be adjusted as necessary to meet the needs and desires of the Association and reflect changing conditions.

We performed this analysis at the request of the Board of Directors of Heritage Place Homeowners Association, Inc. The report is intended for the Association's exclusive use and should not be used for contracting work or relied upon by any other party. The analysis reflects conditions within the property that could be examined visually and is limited to the extent of the report. The analysis is also based upon representations made by Heritage Place Homeowners Association, Inc. in regard to existing reserve fund balances, recent replacements or repairs, and interpretation of the Declarations and Covenants for the project. While reasonable effort was made to ascertain the condition of the property and/or equipment within, it is not to be construed as a guarantee or warranty of the property or equipment therein, nor does it imply that all components will function properly on or after the date of this report. Acceptance of this report by the Association constitutes the agreement of the Association that the liability of Bradley Property Consultants, Inc. for any errors or omissions on negligent misrepresentations herein is limited to the fee paid for this report and that there shall be no liability whatsoever for incidental or consequential damages. Unless otherwise noted in the report, no sampling, testing, or dismantling of any equipment, systems or structural components of the property, other than the visual inspection, was performed. Further, no inspections or tests for soil quality or stability, asbestos, PCBs, or any other hazardous materials were undertaken nor was the quality or adequacy of the water and sewer service to the property analyzed. The inspections addressed herein were not undertaken to address any specific use or purpose contemplated by the Association other than what was stated in the report. This report does not in any way address the property's compliance with any federal, state, or local laws, rules, regulations, or ordinances.

We believe the analysis will provide a useful planning guide. Actual experience in replacing items may differ significantly from the estimates given. Again, we recommend annual updates to the analysis to reflect changes to current conditions.

If you have any questions or require further information, please contact our office at any time.

Very truly yours,

BRADLEY PROPERTY CONSULTANTS, INC.

Stephen M. Bradley President

Enclosures and Attachments: Second Updated 2009 Version

- Replacement and Reserve Analysis Table
- Tables and Graphs of Reserve Balances Over Remaining Life of Components
- Table of Projected Capital Expenses by Year



RESERVE ANALYSIS SECOND 2009 VERSION: 8-3-09

1		
	SED.	ĮĻ
	ğ	POS \$
	8	ZÜ
	ο.	
		ov m
		E K
		SER
		₩ Ž
		7
		######################################
	۵	m F
	Ę	S GE
	XES	BUE
	-	FF FF
	ES	美丽美
	ST	ECON LIFE YRS
	ш	M - 3
	ı	7 5
	ESI	REPL COST
		Transport
	<u></u>	정당
	5	REPL COST
		HI (5 t)
	ST	VAGE ALUE
	ŭ	4 \$
		_≤
		Ę
		ž
		5
1		
		######################################
	,_	
	446	Z
,	its:	Ĕ
10101010101010101	Ē	菜
,	otal units: 446	E
•	F	0

COMMON AREA.

		987,070			DESIRED RESERVES	TOTAL DESIR				
					▶1,152,081		EMENT COS	TOTAL REPLACEMENT COST		
0	0	0						%0		CONTINGENCY
366,874	69,247	987,070								
18,765	3,704	52,800	ო	25	000'09	000'09		-	ST	Rock retaining walls: grout & repair
986	112	1,600	œ	9	8,000	8,000		-	rs	Lighting
393	105	1,500	15	70	000'9	000'9		_	LS	Signage
2,546	145	2,066	4	2	10,328	4.25		2,430	H	Stucco fence: paint & repair
1,952	111	1,584	4	ß	7,920	2.00		3,960	H	Stain wood fence
9,387	2,351	33,516	4	52	39,900	35.00		1,140	느	8' fence: Arapahoe Rd.
61,958	12,230	174,332	က	22	198,105	70.25		2,820		6' fence w/stucco post: Caley Ave.
3,697	421	000'9	∞	9	30,000	30,000		₹-	S	Concrete repairs: walks & pans
6,480	561	8,000	က	2	20,000	20,000		_	S	Landscape refurbish/tree trim
60,323	15,986	227,873	4	32	257,276	1.75	10%	163,350	S	Sprinkler system replace, Phase 3
80,258	16,502	235,224	က	32	257,276	1.75	10%	163,350	S	Sprinkler system replace, Phase 2
120,129	17,018	242,575	2	32	257,276	1.75	10%	163,350	rs	Sprinkler system replace, Phase 1

BPC, Inc., 08/2009

68,668

40 YR AVERAGE ANNUAL CONTRIBUTION

TOTAL INITIAL CONTRIBUTION

TOTAL RESERVES AVAILABLE

366,874

69,247



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

Phone. 303-232-0252 Fax. 303-232-3243

	æ
	A 5
	5 6
	2
	2 = c
	> ~
	4
	3 2 0

	¥ .
	203 8
	S X
	Z 2
	30.

	YEAR 2014 6
	4 4
	280
	₩
	Z 2 v
	5.5
	~
	254
	> 0
	₹ =
	Y E 20
	2 •
	G 6 7
	IR YEAR 9 2010 2
	₹ 8
	287
!	
	Z
	Q
THE THE THE TANK THE	RIPTION
	8
	8
	•

Sprinkler system replace, Phase 1	137,147	257,276	7,351	14,701	22,052	29,403	36,754	44,104	51,455	58,806	66,157
Sprinkler system replace, Phase 2	96,760	177,018	257,276	7,351	14,702	22,052	29,403	36,754	44,105	51,455	58,806
Sprinkler system replace, Phase 3	76,309	136,631	196,954	257,276	7,351	14,702	22,052	29,403	36,754	44,105	51,455
Landscape refurbish/tree trim	7,041	13,520	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000
Concrete repairs: walks & pans	4,118	7,816	11,513	15,210	18,908	22,605	26,303	30,000	3,000	9,000	000,6
6' fence w/stucco post: Caley Ave.	74,188	136,147	198,105	7,924	15,848	23,773	31,697	39,621	47,545	55,469	63,394
8' fence: Arapahoe Rd.	11,738	21,126	30,513	39,900	1,596	3,192	4,788	6,384	7,980	9,576	11,172
Stain wood fence	2,063	4,016	5,968	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168
Stucco fence: paint & repair	2,691	5,236	7,782	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131
Signage	498	891	1,284	1,677	2,070	2,463	2,856	3,249	3,642	4,035	4,428
Lighting	1,098	2,084	3,070	4,056	5,042	6,028	7,014	8,000	800	1,600	2,400
Rock retaining walls: grout & repair	22,469	41,235	000'09	2,400	4,800	7,200	009'6	12,000	14,400	16,800	19,200
BASE RESERVES	436,121	802,996	799,816	372,744	104,018	150,717	197,415	244,113	231,928	259,496	305,311
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	0	(257,276)	(535,381)	(315,424)	0	0	0	(28,000)	(18,248)	0	0
ANNUAL DEPOSIT	366,874	366,874	254,096	108,310	46,698	46,698	46,698	46,698	45,815	45,815	45,815
TOTAL RESERVES	436,121	545.720	264.434	57.320	104.018	150.717	197.415	186.113	213.681	259.496	305,311



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

YEAR 2029 YEAR 2028 YEAR 2927 YEAR 2026 VEAR 2025 YEAR 2024 YEAR 2023 YEAR 2022 YEAR 2021 YEAR 2020 Phone 303-232-0252 Fax 303-232-3243 DESCRIPTION

YEAR 2030 22

COMMON AREA											
Sprinkler system replace. Phase 1	73 507	80.858	88 209	05 560	102 910	110 261	117612	124 963	132 313	139 664	147 015
Sprinkler system replace, Phase 2	66.157	73.508	80,858	88.209	95.560	102,911	110.261	117.612	124.963	132,314	139 664
Sprinkler system replace, Phase 3	58,806	66,157	73,508	80,858	88,209	95,560	102,911	110,261	117,612	124,963	132,314
Landscape refurbish/tree trim	16,000	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000	16,000
Concrete repairs: walks & pans	12,000	15,000	18,000	21,000	24,000	27,000	30,000	3,000	6,000	000,6	12,000
6' fence w/stucco post: Caley Ave.	71,318	79,242	87,166	95,090	103,015	110,939	118,863	126,787	134,711	142,636	150,560
8' fence: Arapahoe Rd.	12,768	14,364	15,960	17,556	19,152	20,748	22,344	23,940	25,536	27,132	28,728
Stain wood fence	4,752	6,336	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168	4,752
Stucco fence: paint & repair	6,197	8,262	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131	6,197
Signage	4,821	5,214	5,607	6,000	300	009	006	1,200	1,500	1,800	2,100
Lighting	3,200	4,000	4,800	2,600	6,400	7,200	8,000	800	1,600	2,400	3,200
Rock retaining walls: grout & repair	21,600	24,000	26,400	28,800	31,200	33,600	36,000	38,400	40,800	43,200	45,600
BASE RESERVES	351,126	396,940	422,755	450,323	490,045	535,767	581,489	569,211	596,685	642,407	688,129
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	0	(20,000)	(18,248)	(6,000)	0	0	(58,000)	(18,248)	0	0	0
ANNUAL DEPOSIT	45,815	45,815	45,815	45,815	45,722	45,722	45,722	45,722	45,722	45,722	45,722
TOTAL RESERVES	351,126	376,940	404,508	444,323	490,045	535,767	523,489	550,963	589,685	642,407	688,129



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

3
3 5 F
₹ ≎ ,
3 O 8
>
3 5 w
3 C
₹ 80 O
H 2 m
~
< 6 0
2 2 4
2
S 25 85
> 2
~
2 8 E
> 0
ž .
EAR 2034 26
Y EAR 2034 26
YEAR 2034 26
YEAR 2034 26
2034 2034 26
AR YEAR 33 2034 5 26

Sprinkler system replace, Phase 1	154,366	161,716	169,067	176,418	183,769	191,119	198,470	205,821	213,172	220,522	227,873
Sprinkler system replace, Phase 2	147,015	154,366	161,717	169,067	176,418	183,769	191,120	198,470	205,821	213,172	220,523
Sprinkler system replace, Phase 3	139,664	147,015	154,366	161,717	169,067	176,418	183,769	191,120	198,470	205,821	213,172
Landscape refurbish/tree trim	20,000	4,000	8,000	12,000	16,000	20,000	4,000	8,000	12,000	16,000	20,000
Concrete repairs: walks & pans	15,000	18,000	21,000	24,000	27,000	30,000	3,000	6,000	000,6	12,000	15,000
6' fence w/stucco post: Caley Ave.	158,484	166,408	174,332	182,257	190,181	198,105	7,924	15,848	23,773	31,697	39,621
8' fence: Arapahoe Rd.	30,324	31,920	33,516	35,112	36,708	38,304	39,900	1,596	3,192	4,788	6,384
Stain wood fence	6,336	7,920	1,584	3,168	4,752	6,336	7,920	1,584	3,168	4,752	6,336
Stucco fence: paint & repair	8,262	10,328	2,066	4,131	6,197	8,262	10,328	2,066	4,131	6,197	8,262
Signage	2,400	2,700	3,000	3,300	3,600	3,900	4,200	4,500	4,800	5,100	5,400
Lighting	4,000	4,800	2,600	6,400	7,200	8,000	800	1,600	2,400	3,200	4,000
Rock retaining walls: grout & repair	48,000	50,400	52,800	55,200	57,600	000'09	2,400	4,800	7,200	009'6	12,000
BASE RESERVES	733,851	759,573	787,047	832,769	878,491	924,213	653,830	641,404	687,126	732,848	778,570
CONTINGENCY	0	0	0	0	0	0	0	0	0	0	0
CAPITAL EXPENSES	(20,000)	(18,248)	0	0	0	(316,105)	(58,148)	0	0	0	(20,000)
ANNUAL DEPOSIT	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722
TOTAL RESERVES	713,851	741,325	787,047	832,769	878.491	608.108	595,683	641.404	687.126	732,848	758.570



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1588 S. Clarkson St., Denver, CO 80210

1588 S. Clarkson St., Denver, CO 80210 Phone 303-232-0252 Fax: 303-232-3243

DESCRIPTION

SECOND 2009 VERSION: 8-3-09

COMMON AREA:							
Sprinkler system replace, Phase 1	235,224	242,575	249,925	257,276	7,351	14,701	22,052
Sprinkler system replace, Phase 2	227,873	235,224	242,575	249,926	257,276	7,351	14,702
Sprinkler system replace, Phase 3	220,523	227,873	235,224	242,575	249,926	257,276	7,351
Landscape refurbish/tree trim	4,000	8,000	12,000	16,000	20,000	4,000	8,000
Concrete repairs: walks & pans	18,000	21,000	24,000	27,000	30,000	3,000	6,000
6' fence w/stucco post: Caley Ave.	47,545	55,469	63,394	71,318	79,242	87,166	95,090
8' fence: Arapahoe Rd.	7,980	9,576	11,172	12,768	14,364	15,960	17,556
Stain wood fence	7,920	1,584	3,168	4,752	6,336	7,920	1,584
Stucco fence: paint & repair	10,328	2,066	4,131	6,197	8,262	10,328	2,066
Signage	5,700	6,000	300	009	006	1,200	1,500
Lighting	4,800	2,600	6,400	7,200	8,000	800	1,600
Rock retaining walls: grout & repair	14,400	16,800	19,200	21,600	24,000	26,400	28,800
BASE RESERVES	804,292	831,767	871,489	917,211	705,656	436,102	206,300
CONTINGENCY	0	0	0	0	0	0	0
CAPITAL EXPENSES	(18,248)	(6,000)	0	(257,276)	(315,276)	(275,524)	0

TOTAL RESERVES
BPC, Inc., 08/2009

45,722

45,722

45,722

45,722

45,722

45,722

ANNUAL DEPOSIT

659,935


871,489

45,722

206,300




rty Inspection • Construction Consultants
1588 S. Clarkson St., Denver, CO 80210
Phone 309-232-0252 Fax 309-232-3243



		RESERVES ON	ERVES ON HAND YEAR 1		\$69,247	>	VALUE OF RESERVE ITEMS	ERVE ITEMS		\$1,152,081	
		ENDING BALAN	NG BALANCE YEAR 11		\$305,311	⋖	AVERAGE CAPITAL EXPENSE	TAL EXPENSE		\$107,666	
		AVERAGE BALANCE	ANCE		\$247,304	⋖	VERAGE DEPOSIT	SIT		\$129,127	
	_	2	ო	4	S	9	7	80	6	10	=
YEAR	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019
CAPITAL EXPENSES	0	(257,276)	(535,381)	(315,424)	0	0	0	(28,000)	(18,248)	0	0
ANNUAL DEPOSITS	366,874	366,874	254,096	108,310	46,698	46,698	46,698	46,698	45,815	45,815	45,815
TOTAL RESERVES	436,121	545,720	264,434	57,320	104,018	150,717	197,415	186,113	213,681	259,496	305,311



1588 S. Clarkson St., Denver, CO 80210 Phone: 303-232-0252 Fax: 303-232-3243




2	ESERVES ON P	ES ON HAND YEAR 12		\$100,113		ALUE OF RESERVE LIEMS	EKVE LEMS	•	L80,261,14	
Ŵ		CE YEAR 22		\$688,129	¥	VERAGE CAPI	TAL EXPENSE		\$10,954	
¥	ш	NCE		\$509,489	¥.	VERAGE DEPC	SIT		\$45,756	
12	13	14	15	16	17	18	19	20	21	22
2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
0	(20,000)	(18,248)	(000'9)	0	0	(28,000)	(18,248)	٥	0	6
45,815	45,815	45,815	45,815	45,722	45,722	45,722	45,722	45,722	45,722	45,722
351,126	376,940	404,508	444,323	490,045	535,767	523,489	550,963	596,685	642,407	688,129
	ш	AVERAGE 2 (20) (30) (316) (316) (316)	AVERAGE 2 (20) (30) (316) (316) (316)	AVERAGE BALANCE YEAR 22 AVERAGE BALANCE 13 14 2021 2022 (20,000) (18,248) 45,815 45,815 376,940 404,508 4	AVERAGE BALANCE 13 14 15 2021 2022 2023 (20,000) (18,248) (6,000) 45,815 45,815 376,940 404,508 444,323	ENDING BALANCE YEAR 22 \$688,129 A AVERAGE BALANCE \$509,489 A 13 14 15 16 17 2021 2022 2023 2024 2025 (20,000) (18,248) (6,000) 0 0 45,815 45,815 45,722 45,722 376,940 404,508 444,323 490,045 535,767	ENDING BALANCE YEAR 22 \$688,129 A AVERAGE BALANCE \$509,489 A 13 14 15 16 17 2021 2022 2023 2024 2025 (20,000) (18,248) (6,000) 0 0 45,815 45,815 45,722 45,722 376,940 404,508 444,323 490,045 535,767	ENDING BALANCE YEAR 22 \$688,129 A AVERAGE BALANCE \$509,489 A 13 14 15 16 17 2021 2022 2023 2024 2025 (20,000) (18,248) (6,000) 0 0 45,815 45,815 45,722 45,722 376,940 404,508 444,323 490,045 535,767	ENDING BALANCE YEAR 22 \$688,129 AVERAGE CAPITAL EXPENSE AVERAGE BALANCE \$509,489 AVERAGE DEPOSIT 13 14 15 16 17 18 19 2021 2022 2023 2024 2025 2026 2027 (20,000) (18,248) (6,000) 0 (58,000) (18,248) 45,815 45,815 45,722 45,722 45,722 45,722 376,940 404,508 444,323 490,045 535,767 523,489 550,963 1	ENDING BALANCE YEAR 22 \$688,129 AVERAGE CAPITAL EXPENSE 4 AVERAGE BALANCE \$509,489 4 4 17 18 19 20 13 14 15 16 17 18 19 20 2021 2022 2024 2025 2026 2027 2028 (20,000) (18,248) (6,000) 0 (58,000) (18,248) 0 45,815 45,712 45,712 45,722 45,722 45,722 45,722 376,940 404,508 444,323 490,045 535,767 523,489 550,963 596,685




Phone: 303-232-0252 Fax 303-232-3243





			一般の 開発を発す しゅうしゅ								
	2	ESERVES ON I	RVES ON HAND YEAR 23	13	\$550,963		/ALUE OF RESERVE ITEMS	ERVE ITEMS		\$1,152,081	
	ū	ENDING BALAN	ANCE YEAR 33		\$758,570		AVERAGE CAPITAL EXPENSE	TAL EXPENSE		\$39,318	
	A	VERAGE BALA	INCE		\$725,202	_	AVERAGE DEPOSIT	DSIT		\$45,722	
	23	24	25	56	27	28	29	30	31	32	33
YEAR	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
CAPITAL EXPENSES	(20,000)	(18,248)	0	0	0	(316,105)	(58,148)	0	0	0	(20,000)
ANNUAL DEPOSITS	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722	45,722
TOTAL RESERVES	713,851	741,325	787,047	832,769	878,491	608,108	595,683	641,404	687,126	732,848	758,570



	₹	RESERVES ON	ON HAND YEAR 34	34	\$641,404	> 	ALUE OF RE	VALUE OF RESERVE ITEMS \$1,152,081
	ũ	NDING BALAN	ANCE YEAR 40		\$206,300	A	VERAGE CA	AVERAGE CAPITAL EXPENSE
	¥	VERAGE BAL	LANCE		\$557,213	¥	VERAGE DEPOSIT	POSIT \$45.722
	34	35	36	37	38	39	4	
YEAR	2042	2043	2044	2045	2046	2047	2048	
CAPITAL EXPENSES	(18,248)	(0000)	0	(257,276)	(315,276)	(275,524)	0	
ANNUAL DEPOSITS	45,722	45,722	45,722	45,722	45,722	45,722	45,722	
TOTAL DECEDIVES	707 046	H74 340	071 400	360 037	300 300	160 870	406 300	



1588 S. Clarkson St., Denver, CO 80210

HERITAGE PLACE HOMEOWNERS ASSOCIATION

RESERVE ANALYSIS- Projected Capital Expenses By Year

SECOND 2009 VERSION: 8-3-09

	<u> </u>
	₹ o
	H 0
	~
	4 8 9
	S (4
	3
	> ~
	7 9 .
	3 6 3
	2
	¥ ≣ r
	> ~

	₹ ₹
	@ 5 Y
	~
	¥ 2 v
	> ~
	5 ~
	7
	3
	<
	7 % °

	×
	¥ 5 °
	>
	₹ 6
	£ 8 -
	<i></i>
	Z
243	Z.
32-3243	C F
03-232-3243	SECTION
ых: 303-232-3243	<u>ပ</u> ပ
52 Fax: 303-232-3243	SES SECTIO
2-0252 Fax: 303-232-3243	WSES SECTIO
1-232-0252 Fax: 303-232-3243	WSES SECTIO
: 303-232-0252 Fax: 303-232-3243	OILUAS SASMANXA
hone: 303-232-0252 Fax: 303-232-3243	EXPENSES SECTIO
Phone: 303-232-0252 Fax: 303-232-3243	EXPENSES SECTIO
Phone: 303-232-0252 Fax: 303-232-3243	EXPENSES SECTIO
Phone: 303-232-0252 Fax: 303-232-3243	WSES SECTIO

COMMON AREA											
Sprinkler system replace, Phase 1	0	257,276	0	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 2	0	0	257,276	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 3	0	0	0	257,276	0	0	0	0	0	0	0
Landscape refurbish/tree trim	0	0	20,000	0	0	0	0	20,000	0	0	0
Concrete repairs: walks & pans	0	0	0	0	0	0	0	30,000	0	0	0
6' fence w/stucco post: Caley Ave.	0	0	198,105	0	0	0	0	0	0	0	0
8' fence: Arapahoe Rd.	0	0	0	39,900	0	0	0	0	0	0	0
Stain wood fence	0	0	0	7,920	0	0	0	0	7,920	0	0
Stucco fence: paint & repair	0	0	0	10,328	0	0	0	0	10,328	0	0
Signage	0	0	0	0	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	0	0	8,000	0	0	0
Rock retaining walls: grout & repair	0	0	000'09	0	0	0	0	0	0	0	0
Capital Expense	0	257,276	535,381	315,424	0	0	0	58,000	18,248	0	0



RESERVE ANALYSIS- Projected Capital Expenses By Year

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

YEAR 2030 YEAR 2029 YEAR 2028 YEAR 2027 YEAR 2826 VEAR 2025 VEAR 2024 YEAR 2023 YEAR 2022 YEAR 2021 Y£AR 2020 CAPITAL EXPENSES SECTION Phone: 303-232-0252 Fax: 303-232-3243

COMMON AREA:		-									
Sprinkler system replace, Phase 1	0	0	0	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 2	0	0	0	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 3	0	0	0	0	0	0	0	0	0	0	0
Landscape refurbish/tree trim	0	20,000	0	0	0	0	20,000	0	0	0	0
Concrete repairs: walks & pans	0	0	0	0	0	0	30,000	0	0	0	0
6' fence w/stucco post: Caley Ave.	0	0	0	0	0	0	0	0	0	0	0
8' fence: Arapahoe Rd.	0	0	0	0	0	0	0	0	0	0	0
Stain wood fence	0	0	7,920	0	0	0	0	7,920	0	0	0
Stucco fence: paint & repair	0	0	10,328	0	0	0	0	10,328	0	0	0
Signage	0	0	0	6,000	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	0	8,000	0	0	0	0
Rock retaining walls: grout & repair	0	0	0	0	0	0	0	0	0	0	0
Capital Expense	0	20,000	18,248	6,000	0	0	58,000	18,248	0	0	0
											l



RESERVE ANALYSIS. Projected Capital Expenses By Year

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

Phone: 303-232-0252 Fax: 303-232-3243

YEAR 2041 YEAR 2040 YEAR 2039 YEAR 2038 YEAR 2837 YEAR 2036 YEAR 2035 YEAR 2034 YEAR 2033 YEAR 2032 YEAR 28.21 CAPITAL EXPENSES SECTION

COMMON AREA											
Sprinkler system replace, Phase 1	0	0	0	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 2	0	0	0	0	0	0	0	0	0	0	0
Sprinkler system replace, Phase 3	0	0	0	0	0	0	0	0	0	0	0
Landscape refurbish/tree trim	20,000	0	0	0	0	20,000	0	0	0	0	20,000
Concrete repairs: walks & pans	0	0	0	0	0	30,000	0	0	0	0	0
6' fence w/stucco post: Caley Ave.	0	0	0	0	0	198,105	0	0	0	0	0
8' fence: Arapahoe Rd.	0	0	0	0	0	0	39,900	0	0	0	0
Stain wood fence	0	7,920	0	0	0	0	7,920	0	0	0	0
Stucco fence: paint & repair	0	10,328	0	0	0	0	10,328	0	0	0	0
Signage	0	0	0	0	0	0	0	0	0	0	0
Lighting	0	0	0	0	0	8,000	0	0	0	0	0
Rock retaining walls: grout & repair	0	0	0	0	0	60,000	0	0	0	0	0
Capital Expense	20,000	18,248	0	0	0	316,105	58,148	0	0	•	20,000



RESERVE ANALYSIS- Projected Capital Expenses By Year

SECOND 2009 VERSION: 8-3-09

1588 S. Clarkson St., Denver, CO 80210

1388 S. Clarkson St., Denver, CO 80210 Phone: 303-232-0252 Fax: 303-232-3243

YEAR 2048 YEAR 39 7 R YEAR 2846 YEAR 2045 YEAR 2044 YEAR 2043 YEAR 2042 CAPITAL EXPENSES SECTION

Sprinkler system replace, Phase 1 0 0 Sprinkler system replace, Phase 2 0 0 Sprinkler system replace, Phase 3 0 0 Landscape refurbish/tree trim 0 0 Concrete repairs: walks & pans 6' fence w/stucco post: Caley Ave. 8' fence: Arapahoe Rd. Stain wood fence 0 0 Stain wood fence: paint & repair Signage 10,328 0 Lighting 0 6,000						
hase 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0						
hase 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0	0	257,276	0	0	0
m 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0	0	0	257,276	0	0
m 0 ans 0 10,328 10,328	0 0	0	0	0	257,276	0
y Ave. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0	0	0	20,000	0	0
y Ave. 0 0 7,920 10,328 0	0 0	0	0	30,000	0	0
7,920 10,328 0	0 0	0	0	0	0	0
7,920 10,328 0 0	0 0	0	0	0	0	0
10,328	7,920 0	0	0	0	7,920	0
0	10,328 0	0	0	0	10,328	0
Lighting 0 0	000'9 0	0	0	0	0	0
	0 0	0	0	8,000	0	0
Rock retaining walls: grout & repair	0 0	0	0	0	0	0
Capital Expense 18,248 6,000		0	257,276	315,276	275,524	0